






PAGER

Version 3

M 5.5, 115km SSW of Merizo Village, Guam

Origin Time: 2019-07-21 17:35:38 UTC (Mon 03:35:38 local) Location: 12.2536° N 144.4078° E Depth: 47.7 km

Created: 6 hours, 34 minutes after earthquake



and economic losses. There is a low likelihood of casualties and damage.

Green alert for shaking-related fatalities Estimated Economic Losses 65% 10,000 100 1,000 100,000 USD (Millions,

Estimated Population Exposed to Earthquake Shaking

ESTIMATED POPULATION EXPOSURE (k=x1000)		_*	_*	0	0	0	0	0	0	0
ESTIMATED MODIFIED MERCALLI INTENSITY			11-111	IV	V	VI	VII	VIII	IX	X+
PERCEIVED SHAKING		Not felt	Weak	Light	Moderate	Strong	Very Strong	Severe	Violent	Extreme
POTENTIAL DAMAGE	Resistant Structures	None	None	None	V. Light	Light	Moderate	Mod./Heavy	Heavy	V. Heavy
	Vulnerable Structures	None	None	None	Light	Moderate	Mod./Heavy	Heavy	V. Heavy	V. Heavy


^{*}Estimated exposure only includes population within the map area.

Population Exposure

population per 1 sq. km from Landscan



Overall, the population in this region resides in structures that are a mix of vulnerable and earthquake resistant construction. The predominant vulnerable building types are informal (metal, timber, GI etc.) and heavy wood frame construction.



Historical Earthquakes

Date	Dist.	Mag.	Max	Shaking
(UTC)	(km)		MMI(#)	Deaths
2001-10-12	88	7.0	VII(48k)	0
2002-04-26	98	7.0	VIII(2k)	0
1993-08-08	96	7.7	IX(3k)	0

Recent earthquakes in this area have caused secondary hazards such as landslides and liquefaction that might have contributed to losses.

Selected City Exposure

from GeoNames.org

MMI City Population

bold cities appear on map.

(k = x1000)

Event ID: us70004q4u

PAGER content is automatically generated, and only considers losses due to structural damage. Limitations of input data, shaking estimates, and loss models may add uncertainty.